

USAG-FWA DPW Environmental Work Order Review			Cultural Resources		
Work Order Number	Building	Description	Steamline Activity	Date Reviewed	Comments
DES-FD023-5J	Multi	Upgrade of Fire Detection Systems	D6	1/7/2016	Record of Environmental Consideration
MED-00006-5J	4076	Expansion of Hospital Parking Lot	D1	1/7/2015	Record of Environmental Consideration/Again?
DT-CRTC-RDECO-G5053	CRTC	Cold Weather Protective Combat Uniform System Evaluation. DTA	D5	1/11/2016	DTA
DT-CRTC-CM2AS-G50	CRTC	Cold Weather Operational Integration Assessment of ArtiX Ahkio Sled	D5	1/11/2016	DTA
DT-CRTC-CM2AS-G5066	CRTC	Cold Weather Operational Integration Assessment of Litefighter CataMount 2 Shelter	D5	1/11/2016	DTA
BEB-15034-5J	Aircraft Ramp, 2077	Paint Outside Grounding Point	D13	1/11/2016	
15C-00002-6J	1060	Install outlets	D1	1/11/2016	
617-00002-5J	2132	Paint Outside Grounding Point	D13	1/11/2016	
125-ARB07-6J	2132	Channel for cables installed	D1	1/11/2016	
DCA-70625-4J	1044	Install Emergency Lighting	D13	1/11/2016	
CRL-00001-6J	CRREL	Install and Repair Fencing	D1	1/13/2016	Surveyed 2011
DPW-15006-5J	3479	Repair Structural Deficiencies in 3479	D1	1/13/2016	Record of Environmental Consideration
CRT-00001-6J	Mobility Test Complex	Repair Well	D2	1/15/2016	DTA, Surveyed 2003
DCA-70667-5J	2092	Demo 2092	D2	1/25/2016	
DPW-15032-5J	BRIDD2	Repair Bridge	D1	1/25/2016	Surveyed 2011
DPW-15040-5J	BRIDD4	Repair Bridge	D1	1/25/2016	Surveyed 2011
DPW-15039-5J	XBRIF	Repair Bridge	D1	1/25/2016	Surveyed 2011
DPW-15031-5J	BRIDD1	Repair Bridge	D1	1/25/2016	Surveyed 2011
AFH-10004-6J	Southern Cross MFH	Demo buildings, install utilities, building pads, and roads	A	1/25/2016	In disturbed ground area 2010, covered in O&M PA
2016-DT-CRTC-PEOCS-G5101	DTA	CRTC natural enviro materials performance evaluation	D5	1/25/2016	
ATEC-2016-DT-CRTC-CM2AS-G50	DTA	Cold Weather Operational Inegration Assessment of the ArctiX Ahkio Sled	D5	1/27/2016	DTA
DCD-00048-5J	1555	Renovate room 116A	D2	1/28/2016	Record of Environmental Consideration
2016-DT-CRTC-STDVH-F9075	DTA	CWT of the Hippo Water Tank	D5	2/8/2016	DTA
N/A	BRTA	High Angle Mountainous Marksmanship Range (HAMMR)	D5	2/8/2016	PEA Range Control Checklist, No Archy concerns, surveyed 08/10/2012
DPW-14039-4J	3021	Repair exit man door access	D2	2/8/2016	
BEB-15033-5J	2077	Painting floor inside hangar-grounding points	D13	2/8/2016	
MED-00003-6J	4076	Switch out Honeywell security system with Siemens	D9	2/8/2016	
MED-00001-6J	4076	Replace fire alarm panel	D6	2/8/2016	
DCA-70671-6J	1045	Add 20 amp circuit	E3	2/9/2016	
DACA85-3-04-150	BRTA, 2019	Renew AT&T contract	N/A	2/9/2016	Report of Availability, Surveyed 2014
MED-00002-6J	4076	Remodel physical therapy clinic	D2		
DPW-16028-6J	Birch Hill Ski	const. and reno of Birch Hill Rec Area	A	2/11/2016	Approval only
LRC-20021-4J	3490	Replace two emergency eye wash and shower stations	D13	2/16/2016	
LST-00017-2J	1051	Install light fixture over handicap entrance		2/17/2016	Insert put into packet, SHPO will be consulted
CID-02081-6J	1051	Installation of soundproofing in CID	D1	2/17/2016	Insert put into packet, as described no SHPO consultation required.
CRT-00004-6J	DTA	Self help trail maintenance	D5	2/18/2016	Surveyed 2003

DACA85-3-04-150	BRTA	License renewal AT&T		2/18/2016	Record of Environmental Consideration/Again?
DACA85-2-89-9, DACA85-2-89-10, DACA85-1-86-71	FWA	Renewal and Amendment of Birchwood Easements-storm drain, sewer line-North Star Alaska Housing Corporation	REC	2/18/2016	Record of Environmental Consideration
CYS-70574-4J	4024	replace emergency lights and exit signs	D13	2/18/2016	
PTM-10015-5J	YTA	Upgrade Transmitter Road	D1	2/19/2016	Surveyed 2013
152-HQ135-6J	DTA	Gray Water Dig Approval	D1	2/23/2016	Surveyed 2004/2005
125-ARB15-6J	FWA	Parking lot updates	D1	2/23/2016	Surveyed 2011
PTM-10015-5J	10008-2J	Install Lighting Protection	D13	2/24/2016	Surveyed 2012
DACA85-1-85-11	DTA	Renewal of AT&T Alaska Alascom Lease	N/A	2/24/2016	Record of Environmenal Consideration
NWT-00311-5J	1063	Arms Room Upgrades	D13	2/25/2016	
28F-50019-5J	3425	Install 5 chain link fence cages inside	D1	2/25/2016	
PTM-10005-5J	5113	Repaint interior	D10	2/26/2016	
DES-FD019-2J	1054, 3004, 4390	Paint Red Reflctive Lines on Ground in Bays and Exterior	D13	2/26/2016	Insert put into packet, 3004 is historic, as described no SHPO consultation required.
DPW-16015-6J	3730	Repair the heating, ventilation and HVAC system	D13	3/2/2016	Record of Environmental Consideration
DPW-16036-6J	4055	Repair water damage	D13	3/4/2016	
AHR-W0019-2J	3470	Extend Motorpool Fence Line	D1	3/8/2016	Surveyed 2010
15I-160001-6J	3214	Repaint S4 office	D10	3/10/2016	
GCD-AOP07-6J	1580	Upgrade electrical breaker and wire installation	D1	3/16/2016	
DPW-10154-0J	multi	Construct Fitness Stations along running route	D3	3/22/2016, 3/30/2016	Surveyed 2010, surveyed 2011
PTM-00002-6J	DTA	TA 502 Circular Bivouac	D5	3/22/2016	Surveyed 2002
PTM-00001-6J	DTA	TA 502 Helicopter LZ Repair	D5	3/22/2016	Surveyed 2005
OCA-70692-6J	2090	Drill into floor to install safe	D1	3/28/2016	
OCA-70689-6J	2090	Install Ecolab Dispensers into walls	D1	3/28/2016	
CRL-00002-5J	Permafrost Tunnel	Install fence	D1	3/25/2016	Record of Environmental Consideration
DPW-16016-6J	4176	HVAC and Control System Repair	D1	3/28/2016	Record of Environmental Consideration
AFH-10005-6J	NHC Maint. Bldg.	New Construction	D5	4/1/2016	Surveyed 2011
DCA-70691-6J	3452	Install bathing suit extractors	D1	4/6/2016	
PXS-00059-6J	3703	Repair range hood	D1	4/6/2016	
321-BN019-6J	3211	Applying white metallic dry erase paint in room 132	D10	4/6/2016	
DPW-160369-6J	3028	Connect electrical service for generator room	D1	4/7/2016	
DPW-16040-6J	FWA	New Construction- VC at main gate	D5	4/11/2016	Surveyed 2011
DPW-16042-6J	3401	Construct 3 Combat Readiness Training Facilities	D5	4/14/2016	Surveyed 2011
DPW-16043-6J	1062	Construct new building (NEC) Network Enterprise Center	D5	4/14/2016	Surveyed 2011
PN 88543	FWA	Network Enterprise Center Construction and Renovation	N/A	4/14/2016	Record of Environmental Consideration
DPW-16041-6J	Close-In Range Complex	Construct Perimeter Fence	D1	4/27/2016	Surveyed 2010
321-BN019-6J	3211	Apply Special Paint Rm 132	D10	4/27/2016	
DES-PMO056-6J	Main Gate	Install Double Swing Gates	D1	4/27/2016	Surveyed 2011
DPW-16042-6J	N/A	Construct Three Physical Fitness Facilities	D5/REC	4/11/2016	Surveyed 2011, Record of Environmental Consideration reviewed as well
USG-00018-5J	3401	Install carpet room 122	D1	5/18/2016	
DPW-16046-6J	3010	Repair/replace roof	D1	5/19/2016	
BEB-16028-6J	Husky Drop Zone	Dig Permit	D5	5/19/2016	Surveyed 2013
DPW-16045-6J	relocatables	disposal of 11 relocatables on Alder Ave.	B	5/19/2016	
BEB-16026-6J	1001	Lighting improvements for parking lots and exterior of building	D13	5/20/2016	Insert put into packet, 1001 is covered under Program Comments for Cold War Unaccompanied Personnel Housing which fulfills Section 106 compliance requirements. It is also outside the NHL and HD boundaries, as described no SHPO consultation required.
AMC-20017-6J	2078	Install 40K above ground JP4 tank	C7	5/20/2016	Insert put into packet. 2078 is not historic, but is within the bounds of the NHL and HD. The new tank will be amongst other, existing tanks, and so not be detrimental to the NHL of HD. As described no SHPO consultation required.
PTM-20000-6J	3437	Install 12 quad outlets room 151	D1	5/26/2016	
PTM-D0003-6J	TA524, TA526	Install 3 sign posts for id of stocked lakes	D11	5/30/2016	Surveyed 2003

BSB-99999-6J	3416	paint interior of dining facility	D10	6/1/2016	
DPW-16048-6J	FWA wide	preventitive maintenance sewage pumping	D1	6/2/2016	Very little info in packet. Spoke with POC, no ground distrubance or digging involved, just flushing of existing systems.
DPW-16050-6J	4024	repair fire alarm system	D9	6/2/2016	
ISC-00009-6J	1060	install exit signs	D9	6/3/2016	
AFH-100016-6J	4350, 4351, 4352	exploratory boring and drilling	D1	6/6/2016	Surveyed 2011
	FWA	Verizon Wireless Tower and License	D1	6/13/2016	REC, Surveyed 2011
DPW-16053-6J	FWA	Repair road and add double swing gates to main gate	D1	6/16/2016	Surveyed 2011
DPW-16052-6J	1043	Repairs to North Post Chapel		6/20/2016	SHPO consultation will be initiated.
DPW-16039-6J	3028	Correct Electrical Service	D1	6/17/2016	Record of Environmental Concern
DPW-16056-6J	3401	Repair the south west wing expansion joint.	D1	6/22/2016	Surveyed 2011
DPW-16054-6J	3010	Repair interior damage to walls and insulation.	D1	6/22/2016	
CYS-70717-6J	4176	Create access pannel for full kitchen hood vent cleaning	D1	6/22/2016	
DPW-16055-6J	Multiple	Lighting Repairs	D1	6/23/2016	Insert put into packet. 2077 is a contributing resource to the Ladd Field NHL and Cold War District. Repair work is confined to the interior and proceed as described. No SHPO consultation required.
ISC-00011-6J	3407	Reconfigure cooling solution	D1	6/28/2016	
DPW-16061-6J	3380	preventative/system maintenance -Stryker Wash	D1	6/28/2016	
DPW-10136-2J	airfield	Seal cracks in airfield pavement system	E1	6/28/2016	Insert put into packet. The airfield is a contributing element of the NHL and HD, repair cracks falls under Criteria E of O&M PA. No SHPO consultation required.
DPW-16007-6J	Freeman Road & Parking lot building 1562	repair pavement	D1	6/29/2016	Surveyed 2016
DPW-16006-6J	Luzon rd	repair pavement	D1	6/29/2016	Surveyed 2011
DPW-16005-6J	Santiago Road	repair pavement	D1	6/29/2016	Surveyed 2010
DPW-16004-6J	Ketcham Road	repair pavement	D1	6/29/2016	Surveyed 2010
DPW-16034-6J	10th Street	repair pavement	D1	6/29/2016	Surveyed 2010
DPW-16001-6J	1044 parking lot	repair pavement	D1	6/29/2016	Surveyed 2010
DACA-85-5-86-20	Rec Camp, Seward	Seward Recreation Camp Lease Renewal, Seward, Alaska	D1	6/29/2016	Record of Environmental Consideration
DPW-16019-6J	3485	Repair damaged bady door	D2	7/5/2016	
DES-PMD58-6J	4056	Place small 8x10 shed outside	D1	7/6/2016	Shed placed on a foundation of concrete blocks. No digging per description.
ROA	3013	Out grant to North Haven Communities	N/A	7/12/2016	
DPW-16051-6J	Runway	Runway deicing operations for Gray Eagle	E1	7/12/2016	This WO discussed the equipment and supplies responsibility for the system that will deice the runways for Gray Eagle operation.
DCA-70704-6J	Birch Hill Ski	Construction of new ski lodge	B	7/12/2016	Construct 18,000 SF ski lodge to replace 3 existing temporary buildings.
CYS-70718-6J	Eng Field	Installation of storage shed	D1	7/21/2016	Site approval only next to ball fields.
PTM-D0005-6J	DTA	Dig 2 gray water pits	D5	7/26/2016	2 6x4x4 ft gray water pits at ISB for Arctic Anvil (appeared to be 5 holes)
3rd-00008-6J	3467	Upgrade room 112	D6	7/26/2016	Install instrusion detection system on outside door, reconfig wall for HVAC unit, install combo lock on inner door, install smoke detection sensors, install additional SIM equip
DPW-16-49-6J	near 3567	Cell tower siting only	D3	7/26/2016	Atlas tower siting 125 ft monopole cell tower just south of Building 3567. Surveyed 2011.
ISC-00010-6J	1060	Install outlets in room 109	D1	7/27/2016	
PTM-10003-6J	YTA	Remove stumps and slash TAs 308 and 309	D5	7/27/2016	Impacts 40.2 acres. Surveyed 2002-2006. Result of Stuart Creek 2 fire of 2013.
574-60001-6J	2074	Paint cement floor	D10	7/29/2016	
REC		Lease to Enterprise Engineering Inc. for inspection of JP-8 Pipeline (Haines Fuel Pipeline)	N/A	7/18/2016	Record of Environmental Consideration.
REC		FY16 Force Structure Actions At FWA	N/A	7/12/2016	Record of Environmental Consideration.
DPW-15024-5J	3452	Pool repair design	D1	8/3/2016	
DES-PM0576J	3025	Construct new fire/police dispatch center inside north end of bldg	D5	8/3/2016	
PTM-10002-6J	TA 114	Training Area Repair of trail, regrade and vegetate	D5	8/4/2016	Surveyed 2011.
PTM-10003-6J	YTA Stuart Creek	Remove stumps and slash TAs 308 and 309	D5	8/4/2016	Portions surveyed 2002, 2003,2005, 2008, and 2010.
AFH-10016-6J	3022	Install portable storage shed in parking lot of building 3022	D1	8/10/2016	

AFH-01017-6J	North Haven Properties	Grind existing tree stumps	D4	8/10/2016	
DES-MPO19-2J	1167	Demo and Replace Guard Shack.	D1	8/11/2016	Surveyed 2010.
PTM-10008-6J	XRANG	Repair power and data on MPMG Range	D5	8/11/2016	Surveyed 2010.
GCD-00018-6J	1555	Replace carpet in offices	D1	8/11/2016	Insert put into packet. Building 1555 is a contributing resource to the NHL and HD. As described, all interior modifications will be interior and will not impact any historically significant exterior or interior features.
USG-62211-6J		Refurbish Archery Range	D5	8/11/2016	No Concerns, surveyed. Have seen this one before.
REC 16-WAIN-8-8		Nautilus Road Maintenance	D5	8/11/2016	Surveyed 2011. Record of Environmental Concern.
DES-FD013-5J, DES-FD014-5J	3711, 3713	Fire System Repairs	N/A	8/24/2016	Record of Environmental Consideration
DACA85-9-98-75		Renewal of Concurrence to the BLM for Great America Mining, FWA	N/A	8/24/2016	Record of Environmental Consideration
DPW-16074-6J	2871	Erect a shed on existing footprint	D1	8/26/2016	Approval only
DPW-16077-6J		Build 40,000 sq ft. facility, tactical readiness training center	D5	8/30/2016	Surveyed 2010.
DPW-16076-6J		3707 Addition, Arctic Readiness Center	D5	8/30/2016	Surveyed 2010.
XRANG		Upgrade mulit-purpose machine gun range	D5	9/7/2016	Surveyed 2010.
YTS(TA 305-306)		YTS TA 305-306 Trail Repair	D5	9/7/2016	Surveyed 2010 and 2016.
DPW-16080-6J		Construct Indoor Firing Range	D5	9/8/2016	Surveyed 2010.
REC		Addition of civilian personnel for IMCOM Insider Threat Task Force	N/A	9/8/2016	Record of Environmental Consideration
DPW-16075-6J	Bailey Bridge	Replace Bridge	D5	9/8/2016	Surveyed 2010.
DPW-16079-6J		Construct standard small design TEMF-Tactical Equipment Maintenance Facility complex, includes motor pool and storage	D5	9/8/2016	Surveyed 2010 and 2011.
CRT-00010-6J	DTA	Install Targets		9/16/2016	Insert put into packet. 4 targets in areas not yet surveyed. 5 target locations located within 1km of archaeological sites. Section 106 consultation required.
DOL-20044-0J	2210	Ground Upgrades	N/A	9/12/2016	Record of Environmental Consideration
GCD-00046-5J	1555	Installation of a light switch	D1	10/24/2016	Insert put into packet. 1555 contributing resources to NHL and HD, as described all interior modifications will be interior and will not impact any historically significant exterior or interior features. Any change will need to be reviewed.
GCD-00047-5J	1555	Painting room 116F	D10	10/24/2016	Insert put into packet. 1555 contributing resources to NHL and HD, as described all interior modifications will be interior and will not impact any historically significant exterior or interior features. Any change will need to be reviewed.
GCD-00041-5J	1555	Removal of paint from Protected Distribution System	D13	10/24/2016	Insert put into packet. 1555 contributing resources to NHL and HD, as described all interior modifications will be interior and will not impact any historically significant exterior or interior features. Any change will need to be reviewed.
JAG-25002-6J	1562	Window repair and replacement		10/28/2016	Insert put into packet. 1562 is a contributing resource to the NHL and HD, and any work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
JAG-25005-6J	1562	Painting exterior		11/1/2016	Insert put into packet. 1562 is a contributing resource to the NHL and HD, and any work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
SAF-00001-4J	1024	Awning over north entrance		11/1/2016	Insert put into packet. 1024 contributing to NHL and HD. Further details of this project should be provided for compliance with Section 106 as the project proposes changes to exterior features. Consultation will begin when appropriate architectural drawings and SOW are submitted to this office for review and consultation purposes.
125-H0001-4J	3401	Fireproof door in basement stairwell	D6	11/2/2016	
DPW-16058-6J	2201-2207	Lower roof repair and correct drainage patterns	Program Comments	11/2/2016	Ammo storage facilities covered under program comments
CHP-00007-4J	3430, 3429	Anti-bird nesting measures	D12	11/3/2016	
AMC-2008-5J	3490	Inspect/repair tailpipe local exhaust ventilation system	D13	11/3/2016	
3RD-00004-5J	3467	Install lightswitch in room 109	D1	11/3/2016	

125-ARB09-6J	2297	Wire white elephants into fire system and test grounding point	D6	11/3/2016	
3RD-00007-6J	3467	Install Electric kill switch 116C	D6	11/3/2016	
DES-PMO42-4J	RVC-01	Visitor Center floor retiling	D1	11/3/2016	
BEB-16025-6J	1001	Emergency Exit Alarms	Program Comments	11/3/2016	Building 1001 is covered under Program Comments for Unaccompanied Soldier Housing
DPW-16092-6J	3722	Move relocatable arms rooms to Building 3722	D9	11/3/2016	
DPW-16094-4J	3443	Move relocatable arms rooms to Building 3443	D9	11/3/2016	
DPW-16091-6J	3409	Move relocatable arms rooms to Building 3409	D9	11/3/2016	
CRT-00002-6J	1928	Design and install cathodic protection for tank	D6	11/3/2016	
DPW-17044-7J	Birch Hill Ski	Install Christmas Tree at Birch Hill	D4	11/3/2016	
CHP-19008-6J	4107	Repair landscape	D4	11/3/2016	
DCA-70724-6J	Golf Course	River bank stabilization	B	11/3/2016	Surveyed 2010
DPW-17021-7J	2121	Hangar EPSS Generator repairs	D1	11/4/2016	
DPW-17022-7J	2132	Hangar EPSS Generator repairs	D1	11/4/2016	
DPW-16066-6J	3490	Replace crane in north bay	D1	11/4/2016	
DPW-17020-7J	1581	Generator repairs	D1	11/4/2016	
ANG-16002-6J	2077	Replace main doors with walls or new doors		11/4/2016	Insert put into packet. 2077 is a contributing resource to the NHL and HD, and any work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
ANG-16001-6J	2077	Repair exterior walls to meet AR 190-51		11/4/2016	Insert put into packet. 2077 is a contributing resource to the NHL and HD, and any work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
ANG-16004-6J	2077	Painting and repair interior walls	E1	11/4/2016	Insert put into packet. 2077 is a contributing resource to the Ladd Field NHL and Cold War District. Repair work is confined to the interior and may proceed as described. No SHPO consultation required.
UG4-00004-6J	1047	Electrical outlook installation	E1	11/4/2016	Insert put into packet. 1047 is a contributing resource to the Ladd Field NHL and Cold War District. Installation work is confined to the interior and may proceed as described. No SHPO consultation required.
ANG-16005-6J	2077	Painting and repair exterior		11/4/2016	Insert put into packet. 2077 is a contributing resource to the NHL and HD, and any work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
JAG-25001-6J	1562	Exterior repair		11/4/2016	Insert put into packet. 1562 is a contributing resource to the NHL and HD, and any work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
DPW-16089-6J	2107	Move relocatable Arms Room to Building 2107		11/4/2016	Insert put into packet. 2107 is a contributing resource to the NHL and HD, and any exterior work done will need to be reviewed for compliance with Section 106 and Secretary of the Interior Standards. Currently, not enough information is included in the workorder to begin the consultation process.
DPW-16090-6J	2110	Move relocatable Arms Room to Building 2110		11/4/2016	Insert put into packet. 2110 is a noncontributing resources to the NHL and HD; however, expansion of the building may have an impact on the historic integrity of the NHL and HD. More information will be required.
GCD-AOP62-5J	Airfield	Correct sign violations on Army Airfield	E1	11/4/2016	Airfield sign repairs falls under Criteria E of the O&M PA currently in place. Project may proceed as described.
DPW-17023-7J	3007	Generator repairs	D1	11/4/2016	3007 is a noncontributing element to the NHL and HD. Generator repair work will not have an impact on the historic integrity of the NHL or HD. Project may proceed.
NWT-BR006-6J	BR 2026	Install ventilation system in carpentry shop	D1	11/4/2016	
DPW-17025-7J	DTA 1928	Repair kitchen range hood exhaust system	D1	11/4/2016	
DPW-17026-7J	BR 2019	Repair kitchen range hood exhaust system	D1	11/4/2016	
NWT-BR007-6J	BR 2019	Repair containment membrane of fueling station	D1	11/4/2016	Surveyed July 2014
DPW-17029-7J	3702	Bowling alley range hood exhaust system repair	D1	11/4/2016	
DPW-17028-7J	3408	Burger King range hood exhaust system repairs	D1	11/4/2016	
DPW-17027-7J	3205	Warrior zone range hood exhaust system repairs	D1	11/4/2016	
DPW-17024-7J	1171	Repair ski lodge range hood exhaust system	D1	11/4/2016	
DPW-16059-6J	3425, 3485, 3490, 3492, 3494, 3496	Repair/modernize VMFs vehicle exhaust systems	D1	11/4/2016	

CHP-00001-6J	3430	Handicap ramp installation	D1	11/7/2016	Surveyed 2010
DPW-16096-6J	3007	Repair eye wash station	D11	11/8/2016	See insert. Building 3007 is a noncontributing feature of the Ladd Field NHL and the Cold War HD. Any interior work will not impact the historic integrity of the NHL or HD
DPW-16097-6J		Repair eye wash station	D11	11/8/2016	See insert. Building 2132 is a noncontributing feature of the Ladd Field NHL and the Cold War HD. Any interior work will not impact the historic integrity of the NHL or HD
125-ARB10-6J	2297	Battery charging facility on east side of building	D1	11/8/2016	Surveyed 2011
DPW-16095-6J	3479	Repair ventilation	D6	11/8/2016	
DPW-17030-7J	3703B	Papa John's pizza range hood exhaust system repairs	D1	11/8/2016	
DPW-17031-7J	3703B	Popeye's range hood exhaust system repairs	D1	11/8/2016	
DPW-17032-7J	3703B	Taco Bell range hood exhaust system repairs	D1	11/8/2016	
DPW-17033-7J	3704	Papa John's range hood exhaust system repairs	D1	11/8/2016	
DPW-17034-7J	3416	DFAC range hood exhaust system repair	D1	11/8/2016	
DPW-17036-7J	4024	CDC #1 range hood exhaust system repairs	D1	11/8/2016	
DPW-17035-7J	3728	DFAC range hood exhaust system repair	D1	11/8/2016	
DPW-17037-7J	4076	BAH DFAC Range hood exhaust system repair	D1	11/8/2016	
DPW-17038-7J	4109	CYS Youth center range hood exhaust system repair	D1	11/8/2016	
DPW-17039-7J	4176	CDC #2 range hood exhaust system repairs	D1	11/8/2016	
DPW-17040-7J	4107	SC Chapel range hood exhaust system repairs	D1	11/8/2016	
DPW-17041-7J	4166	SAS Range hood exhaust system repairs	D1	11/8/2016	
TSO-17001-7J	3491	Install GPS rooftop antenna	D3	11/8/2016	
DPW-16067-6J	OHELE	Clear and remove brush and tree limbs from around power poles and overhead power lines	D4	11/8/2016	Surveyed 2010
SAF-00003-4J	1024	Pave the parking lot in front of building	D1	11/9/2016	Surveyed 2010
CHP-00002-6J	4107	Repair/replace outlets	D1	11/9/2016	
DPW-16027-6J	2297	Install oil/water separator Alarm	D6	11/9/2016	
DPW-16023-6J	2080W	Purchase and Install Aboveground Storage Tank	D1	11/10/2016	Surveyed 2010
DPW-16024-6J	3406	Purchase and Install Aboveground Storage Tank	D1	11/10/2016	Surveyed 2010
DPW-16025-6J	2096	Purchase and Install Aboveground Storage Tank	D1	11/10/2016	Surveyed 2010
DPW-16026-6J	1537	Purchase and Install Aboveground Storage Tank	D1	11/10/2016	Surveyed 2010
GCD-AOP53-5J	15580	Bring concrete utilidor pad to grade	D1	11/10/2016	Surveyed 2010
GCD-AOP61-5J	1558	Bring concrete utilidor pad to grade	D1	11/10/2016	Surveyed 2010
GCD-16021-6J	5009	Purchase and Install Aboveground Storage Tank	D1	11/10/2016	Surveyed 2010
DPW-16022-6J	3015	Purchase and Install Aboveground Storage Tank	D1	11/10/2016	Surveyed 2010
AMC-20002-7J	3416	Paint detail accents in dining area	D10	11/14/2016	
DPW-17044-7J	Birch Hill Ski	Repair Birch Hill Power	D1	11/21/2016	
AFH-10009-7J	NHCC 602	Conduct Geo technical study boring at NHCC 602 and Neely Rd	D4	11/22/2016	Surveyed 2010
SAF-00002-7J	Motorcycle Course	Motorcycle Course Drop Gates/Posts	D1	11/22/2016	Surveyed 2010
DPW-17063-7J	2126	Repair PIV for Fire Protection Line	D1	11/22/2016	Surveyed 2010
DPW-17045-7J	old Raven's Roost RV lot	Lay Down Area for Aleut	D1	11/23/2016	
DPW-10110-2J	4055	Repair Roof Leaks	D1	11/28/2016	
DOL-21004-0J	B3490	Vent Beadblaster Exhaust	D1	11/30/2016	
DPW-17070-7J	ZTAXA	Repair section T28A on Taxiway A	E1	12/2/2016	Insert put into packet. No consultation required, falls under criterion E1: repair.
DPW-17071-7J	ZTAXA	Repair Section T18A on Taxiway E	E1	12/2/2016	Insert put into packet. No consultation required, falls under criterion E1: repair.
152-HQ111-5J	3007	Reinstall antenna platform on roof	D3	12/5/2016	Insert put into packet. No consultation required, building within NHL and HD but not historic.
APVR-1501-1J	1557	Install 3x3 phase electrical outlets for AVCATT & NCM3 Simulators in Hangar 1		12/5/2016	Insert put into packet. SHPO consultation required.
DES-PM002-2J	3028	Pave parking lot	D1	12/6/2016	Surveyed 2010
DES-PMO18-2J	3028	Construct concrete pad and power supply for RMAG	D1	12/7/2016	Surveyed 2011
ISC-00005-7J	1060	Approval Only, New IT house wiring	D1	12/9/2016	
ISC-00004-7J	4076	Replace existing 48 volt DC batteries.	D1	12/9/2016	
ISC-00002-7J	1060	Replace existing 48 volt DC batteries.	D1	12/9/2016	
ISC-00003-7J	3407	Replace existing 48 volt DC batteries.	D1	12/9/2016	
DES-PMO22-3J	3028	Install exterior lights in the parking lot	D13	12/14/2016	Insert put into packet. Building not historic or contributing, but within viewshed.